



DOCUMENT NO: TT-GEN-20-009
 REVISION: 01

TECHNICAL TIP

TITLE: PACKING LIST

Instrument/Model:	All C-Rad Products		
Initiator:	Michael Götz	Date:	2023/12/14
TT Completion Status:	<input type="checkbox"/> Incorporated into Service and/or Training Manual: Manual Document Number: _____ Manual Revision: _____ <input type="checkbox"/> The Service Bulletin is Obsolete <input type="checkbox"/> Other, Explain:		
Systems Affected:	<input checked="" type="checkbox"/> All System in the field <input type="checkbox"/> Selected Systems <input type="checkbox"/> Affected S/N list attached <input type="checkbox"/> None		
Status / Priority	<input type="checkbox"/> Immediate (Open/Schedule Call) <input type="checkbox"/> Perform Next Visit <input checked="" type="checkbox"/> Procedural/Informational (No action needed)		

Purpose:

The packaging list which is content of every delivery has changed. A new field "Received" with attached checkboxes was added. The new form is to report discrepancies between expected goods received and goods received at the shipment.

Definition(s):

Distribution:

- C-Rad Internal
- Distributors
- C-Rad User

Information:

- Each shipment from on today, will come with the new shipping list. When you unpack parts, please mark them as "Received" in the document.
- In case quantity is greater 1, mark the received with the amount received, If full amount is received a check mark is ok.

Packaging list

Catalyst+ System, C-RAD
 SP-003-220125-010-03

Page 1 of 2



Shipping to:

.....

.....

Check amount

Check for be Shipped by supplier

Check for be Shipped by receiver

Products

Supplier Art no	Description	Quantity	Shipped	Received
	Catalyst+ Master Scanner <i>s/n:</i>			
	[300162] Pipe plug	1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	[300222] Wire Hanging Kit (consisting of x1 wire, x1 gripper)	1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	[300538] 2 port USB Fiber Optics Extender (TX Transmitter Module) with USB3 cable, <i>s/n:</i>	1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	[300628] PSU Cable Assembly	1	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	[300624+300625+300636] Inner Assembly B with power manager module and Vialux Scanner mounted	1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
HY-004.02	[300626] Front Cover C Assembly	1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Consisting of the following items:	[300358] LC-LC MM 50/125 Duplex 3m	2	<input checked="" type="checkbox"/>	<input type="checkbox"/> 1
	[300616+IPK0067] Back Cover D Assembly with On/Off button Cable	1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	[300618] Tubular Span	1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

- If missing parts are detected, the filled packaging list **must** be sent together with the replenishment request.
- A replenishment shipment can be only issued when the Packing List is filled by the receiver returned with the replenishment request.